


Sectional Unit Door Saddles

Please note provision must be made on lower outside edge for water damage.


Bronze: Architectural Alloy No. 385

Mill Aluminum: Alloy 63 T5


#8T1 Bronze
#9T1 Aluminum




#8T2 Bronze
#9T2 Aluminum




#8T2E Bronze



#8T3 Bronze
#9T3 Aluminum



#8T4 Bronze
#9T4 Aluminum



#8T5 Bronze
#9T5 Aluminum

