

Sectional Unit Door Saddles


Please note provision must be made on lower outside edge for water damage.

Bronze: Architectural Alloy No. 385

Mill Aluminum: Alloy 63 T5


#8S5 Bronze

#9S5 Aluminum




#8S11 Bronze

#9S11 Aluminum




#8S13 Bronze

#9S13 Aluminum



#8S14 Bronze

#9S14 Aluminum



#8S16 Bronze

#9S16 Aluminum

